



Replacement Notes for : Alisun, 10-pin



Installations Notes:

10-pin Alisun ballast, pictured at left, is replaced by the FA100 ballast using the existing input harness from the tanning unit. The existing 8-pin output harness from the tanning unit plugs directly into the FA100 output connector. Note that the input and output connectors are on opposite ends of the FA100.

Typical Applications:
ETS, ESB, Sunal



FOR TECHNICAL SUPPORT CALL (978) 249-6474



